



# TCI

## Sample Roll Report

### VISION CAMERA CONTINUOUS REAL-TIME INSPECTION SYSTEM

## WebRanger - Job 40671 Report

### Job Summary

Job:	40671
Order Number:	40671
Starting Doff #:	1
Ending Doff #:	1
Start Date/Time:	06/30/2016 11:09:29
End Date/Time:	-----
Material Type:	FEP PG 5MIL 60" Log Roll
Operator:	operator
Inspection Type:	Through Light
Inspection File:	Clear.mcs
JobLength(Ft):	646.44
Web Width(in):	61.21
Job Area(Ft2):	3297.53
Units	English (Ft/in/mil2)
Number of: Lanes:	1
Lane1 Width(in):	61.21
MD Direction	Forward
CD Direction	Forward
MD Offset(Ft):	0

### Defect and Event Summary

Flaws			
Symbol	Flaw Class	Count	Counts per (Ft2)
D	Large DSpot	94	.028506
G	Large BSpot	1	.000303
	<b>Total</b>	95	.028809
Events			
Resume Inspection		0	
Pause Inspection		0	
Density Event		515	
Start Job		1	
End Job		0	

